


INSTRUCTIONS FOR JOINERY SURFACE MOUNTING:

ANGLE ANDY 25, DOWNHILL DAN 10, DOWNHILL DAN 14

FLAT FREDDIE 14, SIDEWAYS SALLY 5,


SIDEWAYS SALLY 20, WHERE'S BEN 25




$2 \mid$ draw a guide line and affix joinery mounting clips to surface

1. DRAW A STRAIGHT LINE ON THE MOUNTING SURFACE FOR JOINERY MOUNTING CLIPS.

2. DRILL MOUNTING HOLES ON GUIDE LINE USING THE TWO OUTER HOLES OF THE JOINERY MOUNTING. IF RECESSING, SEE FIG. 1 BELOW.







WARNING: MOUNTING CLIPS ARE SUITABLE FOR JOINERY INSTALLATIONS ONLY. WHEN MOUNTING TO PLASTERBOARD, EXTRUSION MUST BE SCREW-FIXED. SEE ALTERNATIVE INSTRUCTIONS.



INSTRUCTIONS FOR JOINERY SURFACE MOUNTING:

angle andy 25, downhill dan 10, downhill dan 14 FLAT FREDDIE 14, SIDEWAYS SALLY 5, SIDEWAYS SALLY 20, WHERE'S BEN 25

INSTALL JOINERY MOUNTING CLIPS, EXTRUSION AND MAKE ELECTRICAL CONNECTION.

