



MOUNT EXTRUSION, MAKE ELECTRICAL CONNECTION.

1. DRAW A STRAIGHT LINE ON THE MOUNTING SURFACE TO ALIGN MOUNTING CLIPS.

NOTE: MAXIMUM SPACE BETWEEN MOUNTING CLIPS SHOULD BE 400MM. MOUNTING CLIPS







